

**SECRET**

OUT56440

**SECRET 131446Z**

1965 AUG 13 14 54Z

25X1  
13 AUG 1965

1. CAMERA B 23 WAS USED IN MISSION 8036 FLOWN ON 11 AUGUST 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

## 2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY ATMOSPHERICS.


B. 9R SIDE: SEVERE EMULSION BLISTERS AND A REPAIRED FILM TEAR ARE IN FRAME 2032. A MANUFACTURING SPLICE EXISTS IN FRAME 1137.

C. 9L SIDE: TRANSVERSE PLUS DENSITY STREAKS 0.1" WIDE ARE IN FRAMES 0001, 0002, AND 2061. TWO ROWS OF MINUS DENSITY DOTS SPACED 1.7" APART ARE LOCATED 2.6" AND 3.3" FROM THE INBOARD EDGE OF THE FILM THROUGHOUT THE FIRST 60 FRAMES. A HEAT SPLICE IS BETWEEN FRAMES 313 AND 314.

D. BOTH SIDES: PRESSURE ROLLER STATIC AND EDGE STATIC EXIST ALONG BOTH INBOARD AND OUTBOARD SIDES OF THE FILM THROUGHOUT THE MISSION.

E. THE CAMERA SHUTTER FAILED TO CLOSE PROPERLY RESULTING IN GROSS OVEREXPOSURE OF 15 FRAMES. IN EACH INSTANCE THE FILM WAS TRANSPORTED WITH THE SHUTTER OPEN WHICH CAUSED 1/3 TO 1/2 OF THE ADJACENT 15 FRAMES TO ALSO BE OVEREXPOSED. THERE WERE NO MAJOR PROCESSING MALFUNCTIONS DURING THE MISSION.

COPIES RECEIVED <u>7</u>		
Cy No.	Office	Act.
<u>1</u>	File	
<u>2</u>	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
<u>3,4</u>	TID	<input checked="" type="checkbox"/>
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Declassification Review by  
NGA/DoD**SECRET**

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING OF THE POSITIVE WAS GOOD.

C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 35 PERCENT  
OF THE MISSION.

S E C R E T

-END OF MESSAGE-